

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.





Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG. 1







Fig. 4

Fig. 2

FIG. 7




Fig. 7




Fig. 8

09898736-070304




Fig. 9







Fig. 10






Fig. 12B




Fig. 16




Fig. 14





Fig. 15

09898736-070301
T0E070"9E786860



SECTION C-C

Fig. 17




Fig. 19







Fig. 18

Fig. 20

Fig. 21






09887370.000000







09898736-070301

09893736.070301



107112

09898736-070304
FOE020-9E286860



09898735.070301




Fig. 33




Fig. 34




Fig. 37




Fig. 36

43-106-1250
7-14-2001




Fig. 35




Fig. 38






Fig. 39

SECTION B-B



SECTION A-A
Fig. 42



SECTION F-F
Fig. 47




Fig. 40






Fig. 41

09898736.070301






Fig. 45




Fig. 46




Fig. 48




Fig. 49




Fig. 50









FIG. 57






Fig. 58




Fig. 59




Fig. 60




Fig. 61

FIG. 63





Fig. 63




Fig. 64





FIG. 70 92486860




Fig. 67




Fig. 68




Fig. 73




Fig. 74




Fig. 69




Fig. 70

TOP SECRET 92486860




Fig. 71




Fig. 72

FIG. 75




Fig. 75




Fig. 77




Fig. 76

09898736-070301




Fig. 78




Fig. 79

088736-070301

10





Fig. 80

14

10

12












Fig. 81



09898736-070304




Fig. 89




Fig. 90




Fig. 91




Fig. 92




Fig. 94




Fig. 95




Fig. 96




Fig. 93